

Working area
Work place
Job

Hazardous materials description

CeTePox Resins

Hazards for humans and the environment



Irritating to eyes and skin.
May cause sensitisation by skin contact.
Toxic to aquatic organisms, may cause long-term adverse effects in the aquatic environment.

Safety measures and codes of conduct



Take care to aerate and ventilate the work place properly.
Refrain from smoking, eating and drinking in work and storage rooms. Do not store foodstuffs, drinks and tobacco.
Any trouble is to be immediately reported to superior. Repairs are to be carried out properly and carefully. Pipes are to be emptied completely.
Breakable containers with substances are only to be transported utilizing an outer container (i.e. plastic bucket with handle).

Conduct in case of danger



In case of fire, plant instructions are to be adhered to.
Smaller fires should be extinguished with CO2 or powder fire extinguisher, if necessary with a water jet spray.

First aid



Wash contaminated skin thoroughly with soap and water. If there are large areas of moistened skin, immediately rinse with an emergency shower and remove moistened clothing carefully.
After eye contact, immediately rinse eye for several minutes with water and inform superior.
After internal plant treatment, contact an eye specialist.
After swallowing, drink plenty of water and if available, with an addition of active coal.
Avoid vomiting if possible. In case of unconsciousness, place patient into a stable side position. Go to doctor or call for medical help.
After inhalation, seek for fresh air, rest and warmth. If necessary, inform doctor.

Proper waste disposal



Suck up spilt liquid with a universal binder and as with the waste, hand over to the responsible authority for disposal in a closed container. Even small amounts should not be emptied into the drainage.